

**Inspection Photo**  
**Hilltop Ranch RWF 14-33**  
**API # 045-13828**  
**Inspection # 689302078**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo**  
**Hilltop Ranch RWF 14-33**  
**API # 045-13828**  
**Inspection # 689302078**



**Location Photo #3**



**Location Photo #4, uncontrolled weeds near tank battery**



**Inspection Photo**  
**Hilltop Ranch RWF 14-33**  
**API # 045-13828**  
**Inspection # 689302078**



**Location Photo #5, uncontrolled weeds  
behind separators**



**Location Photo #6, uncontrolled weeds near  
wellheads**



**Inspection Photo**  
**Hilltop Ranch RWF 14-33**  
**API # 045-13828**  
**Inspection # 689302078**



**Location Photo #7, unused equipment**



**Location Photo #8, unused equipment**