

Inspection Photos
Location Name: BMC D pad
Location: 446582



28 well on production



Field ECD units in use

Inspection Photos
Location Name: BMC D pad
Location: 446582



2 risers from separator units, no production tanks on this location



Flow line riser to P Tank separator unit.

Inspection Photos
Location Name: BMC D pad
Location: 446582



Flow line into P tank



Flow line from P Tank to flow back tanks

Inspection Photos
Location Name: BMC D pad
Location: 446582



Flow line risers



Flow line risers

Inspection Photos
Location Name: BMC D pad
Location: 446582



Flow line by passes P Tank on second riser goes straight to flow back tanks



2in line from flow line risers to flow back tanks. No production tanks are set on this pad.

Inspection Photos
Location Name: BMC D pad
Location: 446582



South East view of location



South View of location

Inspection Photos
Location Name: BMC D pad
Location: 446582



West view of location



West NW view of location

Inspection Photos
Location Name: BMC D pad
Location: 446582



North West view of location



Entry looking East

Inspection Photos
Location Name: BMC D pad
Location: 446582



Weeds on the west side of pad outside of the sound wall



Weeds at the west side of pad

Inspection Photos
Location Name: BMC D pad
Location: 446582



Weeds on the west side of pad outside of the sound wall



Fuel tank outside of sound walls, No containment or labels.