

PHOTO: VIEW OF AS-DRILLED LOCATION

CAMERA ANGLE: NORTHERLY




PHOTO: VIEW OF AS-DRILLED LOCATION

CAMERA ANGLE: EASTERLY

BISON OIL & GAS II

STRASSER 1-27
NE 1/4 NE 1/4, SECTION 27, T9N, R60W, 6th P.M.
WELD COUNTY, COLORADO

TAKEN BY	G.W.	08-28-18	
DRAWN BY	C.IVIE	09-04-18	
LOCATION PHOTOS			PHOTO 1



UELS, LLC
 Corporate Office * 85 South 200 East
 Vernal, UT 84078 * (435) 789-1017



PHOTO: VIEW OF AS-DRILLED LOCATION

CAMERA ANGLE: SOUTHERLY



PHOTO: VIEW OF AS-DRILLED LOCATION

CAMERA ANGLE: WESTERLY

BISON OIL & GAS II

**STRASSER 1-27
NE 1/4 NE 1/4, SECTION 27, T9N, R60W, 6th P.M.
WELD COUNTY, COLORADO**



UELS, LLC
Corporate Office * 85 South 200 East
Vernal, UT 84078 * (435) 789-1017

TAKEN BY	G.W.	08-28-18	
DRAWN BY	C.IVIE	09-04-18	
LOCATION PHOTOS			PHOTO 2