

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2018

Submitted Date:

10/02/2018

Document Number:

689701853**FIELD INSPECTION FORM**

Loc ID 335652	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 27 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265443	WELL	SI	09/01/2017	GW	045-09015	CHEVRON 32-7D	PR
265530	WELL	PR	05/01/2012	GW	045-09026	CHEVRON 42-7D	PR
265531	WELL	PR	05/01/2012	GW	045-09025	CHEVRON 43-7D	PR
265532	WELL	PR	05/01/2012	GW	045-09024	CHEVRON 31-7D	PR
265533	WELL	PR	05/01/2012	GW	045-09023	CHEVRON 41-7D	PR
265534	WELL	SI	09/01/2017	GW	045-09022	CHEVRON 33-7D	PR
288551	WELL	PR	09/28/2007	GW	045-13296	CHEVRON 41A-7D	PR
289254	WELL	PR	01/31/2011	GW	045-13708	CHEVRON 41C-7D	PR
289376	WELL	PR	09/28/2007	GW	045-13738	CHEVRON 41D-7D	PR
289422	WELL	PR	09/28/2007	GW	045-13759	CHEVRON 42A-7D	PR
289423	WELL	PR	10/01/2011	GW	045-13758	CHEVRON 31B-7D	PR
289424	WELL	PR	09/28/2007	GW	045-13757	CHEVRON 43B-7D	PR
289425	WELL	PR	09/28/2007	GW	045-13756	CHEVRON 43D-7D	PR
289426	WELL	PR	09/28/2007	GW	045-13755	CHEVRON 43A-7D	PR
289699	WELL	PR	09/28/2007	GW	045-13851	CHEVRON 42D-7D	PR
289700	WELL	PR	09/28/2007	GW	045-13850	CHEVRON 31D-7D	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-580-9382

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Chemical container not in use.		
Corrective Action:	Comply with Rule 603.f .	Date:	11/07/2018

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Fence needs repaired around N.E tank battery.		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	10/19/2018

Equipment:			corrective date
Type: Plunger Lift	# 16		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical container at 33-7D. Not in service. No lid on container.		
Corrective Action:	Install lid on container.		Date: 10/04/2018
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	N.E tank battery			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: S.W tank battery							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	300 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal							
Comment: S.W tank battery							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	300 BBLS	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment: N.E tank battery							
Corrective Action:						Date:	
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities									
Facility ID:	265443	Type:	WELL	API Number:	045-09015	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265530	Type:	WELL	API Number:	045-09026	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265531	Type:	WELL	API Number:	045-09025	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265532	Type:	WELL	API Number:	045-09024	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265533	Type:	WELL	API Number:	045-09023	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	265534	Type:	WELL	API Number:	045-09022	Status:	SI	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	288551	Type:	WELL	API Number:	045-13296	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	289254	Type:	WELL	API Number:	045-13708	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID: 289376	Type: WELL	API Number: 045-13738	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289422	Type: WELL	API Number: 045-13759	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289423	Type: WELL	API Number: 045-13758	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289424	Type: WELL	API Number: 045-13757	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289425	Type: WELL	API Number: 045-13756	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289426	Type: WELL	API Number: 045-13755	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289699	Type: WELL	API Number: 045-13851	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

Facility ID: 289700	Type: WELL	API Number: 045-13850	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing well

Corrective Action:

Date:

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Ditches	Fail					Sediment blockage in ditch behind s.w. tankbattery
Gravel	Pass					
		Ditches	Pass			
		Compaction	Pass			
		Culverts	Pass			
		Gravel	Pass			
Compaction	Pass					

Comment: [Washing of location at N.E. tank battery \(abandoned road entrance\). Sediment in ditch behind S.W. tank battery.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 11/07/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401782443	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4596282
689701854	Inspection 689701853 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4596278