

# Inspection Photos

10/09/2018

Operator: RITCHIE EXPLORATION INC - 74770

Location ID: 309602

Inspection Doc. Number: 682504007

Lincoln County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the well location. Previous inspection required removal of equipment. Photo shows green utility box has been removed, however, the pole, control box and concrete block has not been removed in accordance with 1004.a





**Photo 2:** See comments under photo 1.





**Photo 3:** Photo taken from the well location, facing south. Photo shows access road. Reclamation of the access road, including but not limited to, the removal of gravel, compaction alleviation, recontouring/regrading, removal of cattle guard, any remaining fence and revegetation activities will need to commence immediately upon closure of remediation project #4320.



**Photo 4:** Photo taken from the access road, facing south. See comments under photo 3.





**Photo 5:** Photo taken from the access road, facing south. See comments under photo 3.