

Inspection Photos

10/04/2018

Operator: WESTERN OPERATING COMPANY -
95620

Location ID: 312233

Inspection Doc. Number: 682504011
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312233



Photo 1: Photo taken from the well location. Photo of sign at well.



Photo 2: Photo taken at well location. Photo shows two (2) barrels without secondary containment.

Inspection Photos
Operator: WESTERN OPERATING COMPANY - 95620
Location ID: 312233



Photo 3: Photo taken from the meter shed, southwest of the well (40.905553/-103.247635). Photo shows two barrels without secondary containment.



Photo 4: Photo taken from the meter shed, SE of the well. Photo shows fiberglass tank that appears to have tipped over.



Photo 5: Continued from photo 4. Photo shows tank without appropriate labeling.



Photo 6: Photo of meter showing equipment is associated with the “Roper “E-1X”