

Inspection Photos

Operator: BP America

API: 05-067-07204

Date: 10/03/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is well established in this portion of the interim reclamation area and comprised of grasses such as smooth brome (*Bromus inermis*), sand dropseed (*Sporobolus airoides*) and ponderosa pine trees (*Pinus ponderosa*).



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of Canada thistles (*Cirsium arvense*) within the western project area.