

Final Reclamation Inspection

October 10, 2018

Operator: EXTRACTION OIL & GAS INC - #10459

API: 05-123-19451

Inspection Document #: 682404062

Weld County, CO

NWNW Section 9 T5N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WSC #11-9
API: 05-123-19451



Photo 1. Photo taken from the western location, facing East. No visual evidence of equipment on location. Appears the Operator has performed final reclamation activities. Location will remain in-process. Portions of the location do not have uniform vegetative growth.



Photo 2. Photo taken from the western location, facing Southeast. See comments under Photo 1.

Inspection Photos
Location Name: WSC #11-9
API: 05-123-19451



Photo 3. Photo taken from the northern location, facing East. Photo illustrates bare patches with little to no germination of desirable species.



Photo 4. Photo taken from the southern location, facing South. Photo illustrates uniform vegetative growth which is not consistent throughout the location.