

Inspection Photos
Location Name: Howell 1-11
Location ID: 320320



Photo 1 PU




Photo 2 TNK BTRY

Inspection Photos
Location Name: Howell 1-11
Location ID: 320320



Colorado Oil and Gas Conservation Commission
39.88492, -104.28922, 1529.2m
Oct 11, 2018 14:15:36



Colorado Oil and Gas Conservation Commission
39.88533, -104.28907, 1527.4m
Oct 11, 2018 14:13:26

Photo 3 Meter house

Photo 4 Stained soil WH

Inspection Photos
Location Name: Howell 1-11
Location ID: 320320



Photo 5 Hole next to PU base



Photo 6 Unused tubing next to PU

Inspection Photos
Location Name: Howell 1-11
Location ID: 320320



Photo 7 stained soil PU motor



Photo 8 Stained soil Sep

Inspection Photos
Location Name: Howell 1-11
Location ID: 320320



Photo 7 stained soil PU motor