

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/04/2018

Submitted Date:

10/05/2018

Document Number:

685100516

FIELD INSPECTION FORM

Loc ID 315412 Inspector Name: NEIDEL, KRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 82440
Name of Operator: STEHLE OIL COMPANY
Address: P O BOX 1577
City: CRAIG State: CO Zip: 81626

Findings:

- 6 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------|---------|
| Cary, Stehle | | carystehle@gmail.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 113019 | PIT | AC | | | - | PINNACLE 10-30 | EI |
| 230790 | WELL | PR | 05/01/2018 | OW | 103-08459 | PINNACLE UNIT 10-30 | EI |

General Comment:

On 9/4/2018 COGCC Staff, Kris Neidel Inspected the Pinnacle Unit #10-30 well as a follow up to inspection 685100500 (8/20/2018) and complaint number 200446158. Trash, in the form of oil saturated booms and contaminated soils (in pit) were mentioned in 8/20/2018 inspection, were still present on 9/4/2018. Water should be treated prior to being placed in a pit, per rule 907.c(1). The pit should be free of hydrocarbon per rule 902.c. All Photos were taken by Kris Neidel on 9/4/2018.

| Location | | | |
|--|--|--------|-------------------------|
| Lease Road: | | | |
| Type | | | |
| comment: | | | |
| Corrective ActionL | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. No contents or capacity on tank labels. Only NFPA diamonds present. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | | Date: <u>10/26/2018</u> |
| Type | BATTERY | | |
| Comment: | Sign not posted or information inaccurate at well(s) or battery. No battery sign. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | | Date: <u>10/26/2018</u> |
| Emergency Contact Number: | | | |
| Comment: | <input style="width: 100%;" type="text"/> | | |
| Corrective Action: | <input style="width: 100%;" type="text"/> | | Date: _____ |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Noxious and annual weeds on location. | | |
| Corrective Action: | Comply with Rule 603.f . | | Date: <u>09/11/2018</u> |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| Crude Oil | Pump Jack | | |
| Comment: | Stained soil at wellhead. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | | Date: <u>09/28/2018</u> |
| Crude Oil | Tank | | |
| Comment: | Stained soil in multiple places at bases of both tanks. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | | Date: <u>09/28/2018</u> |
| In Containment: <u>No</u> | | | |
| Comment: | <input style="width: 100%;" type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 113019 Type: PIT API Number: - Status: AC Insp. Status: EI

Facility ID: 230790 Type: WELL API Number: 103-08459 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401786059 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4600197 |
| 685100517 | insp photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4600196 |