

PA 22-25
Api# 045-14950
Inspection # 689701900



Location photo

PA 22-25
Api# 045-14950
Inspection # 689701900



Unused equipment at wells

Dead weed debris at wells

PA 22-25
Api# 045-14950
Inspection # 689701900



Unused equipment

PA 22-25
Api# 045-14950
Inspection # 689701900



No capacity on tank

PA 22-25
Api# 045-14950
Inspection # 689701900



Fluid in secondary containment