

Location Name: H&M Petroleum (Highball #1 075-09345)

Inspection Date: 8/13/2018



Photo # - 1




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: H&M Petroleum (Highball #1 075-09345)
Inspection Date: 8/13/2018



Photo # - 2



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: H&M Petroleum (Highball #1 075-09345)

Inspection Date: 8/13/2018



Photo # - 3

Unused flowline riser in the southeast corner of the separator berm



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: H&M Petroleum (Highball #1 075-09345)

Inspection Date: 8/13/2018



Photo # - 4



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: H&M Petroleum (Highball #1 075-09345)

Inspection Date: 8/13/2018



Photo # - 5

Chemical drum requires secondary containment – remove unused drums



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: H&M Petroleum (Highball #1 075-09345)

Inspection Date: 8/13/2018



Photo # - 6

Separator outfall to production pit. No pit permit (Form 15) on file



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources