

**Inspection Photo
GMR 27-2B1
API # 045-07941
Inspection # 689302122**



Location Photo #1



Location Photo #2,

**Inspection Photo
GMR 27-2B1
API # 045-07941
Inspection # 689302122**



Location Photo #3, Unused flow line risers

Location Photo #4, Unused flow line risers

**Inspection Photo
GMR 27-2B1
API # 045-07941
Inspection # 689302122**



Location Photo #5, unused flow line riser



Location Photo #6, Unmarked deadman East end of location.

**Inspection Photo
GMR 27-2B1
API # 045-07941
Inspection # 689302122**



Location Photo #7, Stained rock in battery containment.