

**Inspection Photo
GMR 27-7D
API # 045-09843
Inspection # 689302132**



Location Photo #1

Location Photo #2

**Inspection Photo
GMR 27-7D
API # 045-09843
Inspection # 689302132**



Location Photo #3, unmarked deadman East of Separator



Location Photo #4, unmarked deadman East of Separator

**Inspection Photo
GMR 27-7D
API # 045-09843
Inspection # 689302132**



Location Photo #5 2-unmarked dead man