

**Inspection Photo
GMR 27-14A
API # 045-15774
Inspection # 689302134**



Location Photo #1



Location Photo #2



**Inspection Photo
GMR 27-14A
API # 045-15774
Inspection # 689302134**



Location Photo #3, Oily stained rock in battery containment.



Location Photo #4, Oily stained rock in battery containment.

Inspection Photo
GMR 27-14A
API # 045-15774
Inspection # 689302134



**Location Photo #5, Oily stained rock in
battery containment.**