

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/15/2018

Submitted Date:

10/15/2018

Document Number:

689302134**FIELD INSPECTION FORM**

Loc ID 335351	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>19</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	<a href="#">all Piceance inspections</a>

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271591	WELL	PR	11/22/2004	GW	045-09903	GMR 28-10D (M27NW)	PR
271592	WELL	PR	11/28/2005	GW	045-09904	GMR 27-12D(M27NW)	PR
271608	WELL	PR	11/25/2004	GW	045-09906	GMR 27-13D(M27NW)	PR
271698	WELL	PR	11/21/2005	GW	045-09935	GMR 28-9D (M27NW)	PR
271761	WELL	PR	11/24/2004	GW	045-09947	GMR 28-16D(M27NW)	PR
272099	WELL	PR	11/19/2004	GW	045-10024	GMR 28-8D (M27NW)	PR
295484	WELL	PR	03/18/2009	GW	045-15773	GMR 27-13A (M27NW)	PR
295485	WELL	PR	04/29/2009	GW	045-15774	GMR 27-14A(M27NW)	PR
295488	WELL	PR	04/19/2009	GW	045-15775	GMR 27-11D (M27NW)	PR
295489	WELL	PR	04/29/2009	GW	045-15776	GMR 27-12A(M27NW)	PR
296343	WELL	PR	04/16/2009	GW	045-15993	GMR 27-13B (M27NW)	PR
296344	WELL	PR	04/16/2009	GW	045-15994	GMR 27-12B (M27NW)	PR

<b>General Comment:</b> <a href="#">Routine Field Inspection.</a>
--

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

**Good Housekeeping:**

Type

OTHER

Comment: Oily stained rock in battery containment

Corrective Action: Properly treat or dispose of oily waste in accordance with Rule 907.e.

Date: 11/15/2018

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

# 2

Comment: Chemical units at wellhead

Corrective Action:

Date:

Type: Bird Protectors

# 6

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 12

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 11

Comment:

Corrective Action:

Date:

Type: Other

# 1

Comment: Blow down vessel near tank battery.

Corrective Action:

Date:

Type: Emission Control Device

# 1

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		,	

Comment:	Centralized battery
----------	---------------------

Corrective Action:		Date:	
--------------------	--	-------	--

**Paint**

Condition	Adequate	
Other (Content)	Methanol tank	
Other (Capacity)	1000 gallon	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment:	
----------	--

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	271591	Type:	WELL	API Number:	045-09903	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	271592	Type:	WELL	API Number:	045-09904	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	271608	Type:	WELL	API Number:	045-09906	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	271698	Type:	WELL	API Number:	045-09935	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	271761	Type:	WELL	API Number:	045-09947	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	272099	Type:	WELL	API Number:	045-10024	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	295484	Type:	WELL	API Number:	045-15773	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	295485	Type:	WELL	API Number:	045-15774	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			

<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	295488	Type:	WELL
API Number:	045-15775	Status:	PR
Insp. Status:	PR		
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	295489	Type:	WELL
API Number:	045-15776	Status:	PR
Insp. Status:	PR		
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	296343	Type:	WELL
API Number:	045-15993	Status:	PR
Insp. Status:	PR		
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	296344	Type:	WELL
API Number:	045-15994	Status:	PR
Insp. Status:	PR		
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Ditches						
Slope Roughening						
Berms						
		Compaction				
				Material Handling And Spill Prevention		
Seeding						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302135	Inspection photo 689302135	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4609768">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4609768</a>