

Inspection Photos
Location Name: Surprise Unit 2-08H
API: 05-057-06526



Photo 1. Overview of location taken at entrance facing north.



Photo 2. Cuttings berm pushed in; compromised.