

Inspection Photos

Location Name: Sitzman 1U Location ID 319532, Remediation Project #11252

Inspection Date: 10/17/2018



Photo 1 – Photo of continuous sampler at BH03, 9-14' below surface. Note low recovery of material in sampler, saturated sand, and hydrocarbons in sampler barrel.



Photo 2 – Photo of continuous sampler at BH03, 19-24' below ground surface. Top of sampler is to right of photo. Approximately 50% recovery of material in this sample. Shallower material exhibits impact. Deeper material to left appears non-impacted.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources