

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Oct 16, 2018 10:41:09 AM MDT
Server Receive Date:	Oct 16, 2018 10:41:36 AM MDT
Reference Number:	20181016-1889534898
Location:	557 Airpark Dr, Durango, CO 81303, USA Oct 16, 2018 10:40:24 AM MDT [View Map]

Information

Name	reclamationtablet
Date	Sep 25, 2018
Well Name	SPANISH FORK GAS UNIT B 1
API Number	50670703700
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Completed work description

Notes

mowed weed debris

sign is not on site