

Inspection Photos

Location Name: Bashor PC / AA17-23

Location #: 306260



Colorado Oil & Gas Conservation Commission
40.48317, -104.45633, 1403.0m, 91°
2018/09/25 02:37:49 PM

Photo #1

Bashor PC AA17-23 (API # 05-123-24320) wellhead

SI - Casing Leak

Observed audible venting from bottom of well casing head (Dry vapor - No fluid) – *from prev FIR*



Colorado Oil & Gas Conservation Commission
40.4832, -104.45625, 1412.0m, 184°
2018/10/18 05:04:35 PM

Photo #2

Bashor PC AA17-23 Wellsite

SI - New Csg head, Collar, & Master valve

Phone & Emergency contact info posted



Inspection Photos

Location Name: Bashor PC / AA17-23

Location #: 306260



Photo #3

Bashor PC AA17-23 Battery

From previous FIR

