

Bosely SG 41-27
Api# 05-045-11806
Inspection # 689701926



Battery sign

Bosely SG 41-27
Api# 05-045-11806
Inspection # 689701926



View of labels on tanks.

Bosely SG 41-27
Api# 05-045-11806
Inspection # 689701926



Label peeling.

Bosely SG 41-27
Api# 05-045-11806
Inspection # 689701926



Old label on back of tank.

Bosely SG 41-27
Api# 05-045-11806
Inspection # 689701926



Dead weed debris on location.

Bosely SG 41-27
Api# 05-045-11806
Inspection # 689701926



Dead weed debris on location.

Bosely SG 41-27
Api# 05-045-11806
Inspection # 689701926



Dead weed debris on location.