

Inspection Photos

Location Name: Rabbit Ears O681 23 Location ID 449274



Location 449274.



Snow and snow melt across Location.

Inspection Photos

Location Name: Rabbit Ears O681 23 Location ID 449274



Open ended hose.



Appears to be hydrocarbon sheen in snow melt.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rabbit Ears O681 23 Location ID 449274



Appears to be hydrocarbon sheen in snow melt.



Appears to be hydrocarbon sheen in snow melt.

Inspection Photos
Location Name: Rabbit Ears O681 23 Location ID 449274



API 057-06598.



Tank, placard, but not labeled.