

Inspection Photos
Location Name: UPV 7-15 N3
Location ID: 320400



Photo 1 TNK BTRY

Photo 2 Sep and meter run

Inspection Photos
Location Name: UPV 7-15 N3
Location ID: 320400



Photo 3 Knock out tank to ECD off crude oil tank

Photo 4 Produced water tank

Inspection Photos
Location Name: UPV 7-15 N3
Location ID: 320400



Photo 5 ECD not burning



Photo 6 Pilot failure to ECD