

Inspection Photos  
Location Name: Deal Gulch 1-16  
Location ID: 428535



**Photo 1. Overview of location taken at entrance facing southeast.**



**Photo 2. Stained soil at wellhead..**



Inspection Photos  
Location Name: Deal Gulch 1-16  
Location ID: 428535



**Photo 3. Stained soil at wellhead.**



**Photo 4. Fluid in cellar.**



Inspection Photos  
Location Name: Deal Gulch 1-16  
Location ID: 428535



**Photo 5. Stained soil at wellhead.**



**Photo 6. Fluid in cellar.**



Inspection Photos  
Location Name: Deal Gulch 1-16  
Location ID: 428535



**Photo 7. No wellhead sign.**



**Photo 8. Stained soil at wellhead, bucket with fluid on right side.**



Inspection Photos  
Location Name: Deal Gulch 1-16  
Location ID: 428535



Photo 9. Fluid in bucket.



Photo 10. Soil staining at pump jack exhaust.