

Inspection Photos  
Location Name: Roundup 22-24D  
API: 05-081-07336



**Photo 1. Overview of location taken at entrance facing northwest.**



**Photo 2. Tubing stored at wellhead.**