

## Inspection Photos


Location Name: 05-103-10203 (BANTA RIDGE FED 8-9-1-103)

Location ID: 316305

Inspection: 679701314



**Location**



**Missing bird protection on separator stack**




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: 05-103-10203 (BANTA RIDGE FED 8-9-1-103)

Location ID: 316305

Inspection: 679701314



**Apparent small leak at well head on line to separator**



**Small leak at well head on line to separator ~10" below ground level.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources