

## Inspection Photos

Location Name: 05-103-10064 (BANTA RIDGE FED 3-9-1-103)

Location ID: 316230

Inspection: 679701318



Location



Deadman anchor without marker



## Inspection Photos

Location Name: 05-103-10064 (BANTA RIDGE FED 3-9-1-103)

Location ID: 316230

Inspection: 679701318



**Tank rusty. No holes identified in sides.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources