

Inspection Photos

Location Name: 05-103-10254 (FIGURE FOUR 8016B P16 498)

Location ID: 316326

Inspection: 679701213



Location



Hole in tank battery liner