

Inspection Photos

Location Name: 05-103-10255 (FIGURE FOUR 812D L14 498)

Location ID: 316327

Inspection: 679701215



Location



Riser without end sealed or locked out tag out. Located next to building.

Inspection Photos

Location Name: 05-103-10255 (FIGURE FOUR 812D L14 498)

Location ID: 316327

Inspection: 679701215



Methanol tank label not readable

