

Inspection Photos

Location Name: 05-103-09183 (Carney 3-4)

Location ID: 315757

Inspection: 679701130



Location



Missing tank capacity



Inspection Photos

Location Name: 05-103-09183 (Carney 3-4)

Location ID: 315757

Inspection: 679701130



Berm worn down by off loading valve



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources