

Inspection Photos

Location Name: 05-103-08814 (Carney 39X4)

Location ID: 315611

Inspection: 679701138



Location



Trash - Unused pipe on ground

Inspection Photos

Location Name: 05-103-08814 (Carney 39X4)

Location ID: 315611

Inspection: 679701138



Sign missing the nearest public access road and not fully viewable due to equipment partial blocking sign.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources