

Inspection Photos

Location Name: 05-103-08599 (COOR 4-15)

Location ID: 315495

Inspection: 679701167



Location



Anchor without marker



Inspection Photos

Location Name: 05-103-08599 (COOR 4-15)

Location ID: 315495

Inspection: 679701167



Several unused pipes on ground



Empty pails on location



Inspection Photos

Location Name: 05-103-08599 (COOR 4-15)

Location ID: 315495

Inspection: 679701167

Gas venting



Gas venting around exterior of tubing



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources