

Inspection Photos

Location Name: 05-103-07259 (TRAIL CANYON 24-4)

Location ID:314794

Inspection: 679701188

Venting Gas



Location



Tubing gas venting through valve

Inspection Photos

Location Name: 05-103-07259 (TRAIL CANYON 24-4)

Location ID:314794

Inspection: 679701188

Venting Gas



Tubing gas venting through valve



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources