

Inspection Photos

Location Name: 05-045-09421 (FIGURE FOUR UNIT 8001D A24 498)

05-045-10026 (FIGURE FOUR UNIT 8008B A24 498)

Location ID: 335775

Inspection: 679701191



Location



1 of 8 holes in tank battery berm liner