

## Inspection Photos

Location Name: 05-103-08130 (FEDERAL 10-2)

Location ID: 315240

Inspection: 679701263

Gas leakage



Location



Gas leakage at well head around tubing

## Inspection Photos

Location Name: 05-103-08130 (FEDERAL 10-2)

Location ID: 315240

Inspection: 679701263



**Tubing valve partially open**



**Casing valve partially open**





## Inspection Photos

Location Name: 05-103-08130 (FEDERAL 10-2)

Location ID: 315240

Inspection: 679701263

Gas coming out here



Gas existing into pit from pipe that comes from separator



Casing pressure 350 psi



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: 05-103-08130 (FEDERAL 10-2)

Location ID: 315240

Inspection: 679701263



**No netting on pit**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources