

Inspection Photos


Location Name: 05-103-08420 (EVACUATION CREEK UNIT 7610)

Location ID: 315385

Inspection: 679701411



location



Gas leaking at plunger threads

Inspection Photos

Location Name: 05-103-08420 (EVACUATION CREEK UNIT 7610)

Location ID: 315385

Inspection: 679701411



Gas leaking

Gas leaking at plunger threads



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources