


Inspection Photos

Location Name: 05-103-06417 (AC MCLAUGHLIN 49X)

Location ID: 314694

Inspection: 679701442



location



Unused deadman lying on ground.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources