

**Inspection Photo
Geiske 42A-26
API # 045-14323
Inspection # 689302165**



Location Photo #1



Location Photo #2

**Inspection Photo
Geiske 42A-26
API # 045-14323
Inspection # 689302165**



Location Photo #3



Location Photo #4, unused equipment at wellheads.

**Inspection Photo
Geiske 42A-26
API # 045-14323
Inspection # 689302165**



Location Photo #5, Missing information