

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2018

Submitted Date:

10/22/2018

Document Number:

689701963

FIELD INSPECTION FORM

Loc ID 335641 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

OGCC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------|-------|---------------------------------------|---------------------------|
| , Caerus Piceance | | COGCC.inspections@caerusoilandgas.com | Piceance inspections only |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 286473 | WELL | PR | 11/15/2012 | GW | 045-12679 | N PARACHUTE WF13D-30A36A596 | PR |
| 286474 | WELL | PR | 11/15/2012 | GW | 045-12678 | N PARACHUTE WF04A-31A36A596 | PR |
| 286475 | WELL | PR | 11/15/2012 | GW | 045-12677 | N PARACHUTE WF01B-36A36A596 | PR |
| 286476 | WELL | PR | 11/15/2012 | GW | 045-12682 | N PARACHUTE WF01D-36A36A596 | PR |
| 286477 | WELL | PR | 11/15/2012 | GW | 045-12683 | N PARACHUTE WF04D-31A36A596 | PR |
| 286478 | WELL | PR | 11/15/2012 | GW | 045-12684 | N PARACHUTE WF04B-31A36A596 | PR |
| 289754 | WELL | PR | 11/15/2012 | GW | 045-13879 | N PARACHUTE WF04C-31A36A596 | PR |
| 289819 | WELL | PR | 11/15/2012 | GW | 045-13884 | N PARACHUTE WF04E-31A36A596 | PR |

General Comment:

Routine General Field Inspection

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------------|----------------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | CONTAINERS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------|--------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 970-285-2615 | | |
| Corrective Action: | | | Date: _____ |

| | | | |
|---------------------------|-------|--|-------|
| Good Housekeeping: | | | |
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|----|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------|--|--|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |

Corrective Action:

Date:

| Inspected Facilities | | | | | | | | | |
|-----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 286473 | Type: | WELL | API Number: | 045-12679 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 286474 | Type: | WELL | API Number: | 045-12678 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 286475 | Type: | WELL | API Number: | 045-12677 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 286476 | Type: | WELL | API Number: | 045-12682 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 286477 | Type: | WELL | API Number: | 045-12683 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 286478 | Type: | WELL | API Number: | 045-12684 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 289754 | Type: | WELL | API Number: | 045-13879 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | 289819 | Type: | WELL | API Number: | 045-13884 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing well | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | Ditches | Pass | | | |
| | | Gravel | Pass | | | |
| | | Compaction | Pass | | | |
| Gravel | Pass | | | | | |
| | | Culverts | Pass | | | |
| | | | | Material Handling And Spill Prevention | Pass | |
| Compaction | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 689701964 | Inspection 689701963 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4619418 |