

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/24/2018

Submitted Date:

10/24/2018

Document Number:

692600614

FIELD INSPECTION FORM

Loc ID 303146 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 13 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252547	WELL	PR	07/18/1980	GW	125-06423	WAKEFIELD 1-13	PR

General Comment:

Routine Inspection

Location			
Lease Road:			
Type	Access		
comment:	Trail through CRP		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Lease sign by meter shed for Deterding 14-18		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign at meter run		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Meter run and pig station 3/4 fenced with metal panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead, (VGS and meter shed for Deterding 14-18)		
Corrective Action:		Date:	
Equipment:			
Type: Vertical Separator	# 2		corrective date
Comment:	Vertical gas separator 50% buried by meter shed for Deterding 14-18 Vertical gas separator 50% buried by meter run for Wakefield 1-13 330' SW		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Meter shed for Deterding 14-18 by unit Meter run for Wakefield 1-13 330' SW of wellhead		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	Launching station next to meter run		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and telemetry equipment at meter run		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 252547 Type: WELL API Number: 125-06423 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Meter run for Deterding 14-18 next to wellhead. Meter run for Wakefield 1-13 is 330' SW of wellhead on north side of CR 33](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT