

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2018

Submitted Date:

10/24/2018

Document Number:

692600630**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 411774      Welsh, Brian      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS      State: MT      Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301925	WELL	PR	10/11/2011	GW	125-11673	JONES 43-18 1N44W	PR

**General Comment:**Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at wellhead		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Metal panels around meter shed and metal shed		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter run in metal shed		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:	Vertical gas separator 50% buried by meter shed Vertical gas separator in metal shed		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	



Inspected Facilities									
Facility ID:	301925	Type:	WELL	API Number:	125-11673	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT