

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2018

Submitted Date:

10/24/2018

Document Number:

692600635**FIELD INSPECTION FORM**
 Loc ID 413676 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
411883	WELL	PR	10/10/2011	GW	125-11698	Jones 32-18 1N44W	PR

General Comment:Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at wellhead		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sticker on water tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign mounted to fence at tank battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Metal panels around water tank and metal shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 2		
Comment:	Vertical gas separator 50% buried by meter shed Vertical gas separator in metal shed		
Corrective Action:		Date:	

Type: Ancillary equipment	# 2	
Comment:	Telemetry equipment and electric panel at tank battery	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Meter run is 100' east of wellhead	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		40.052240,-102.328350
Comment:	Boost station is 1000' SE of wellhead				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 411883	Type: WELL	API Number: 125-11698	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT