

Inspection Photos
Location Name: HSR Lonnie 11-8
Location ID: 320449



Photo 1 PU unused equipment fly wheel guard



Photo 2 Stained soil PU Motor

Inspection Photos
Location Name: HSR Lonnie 11-8
Location ID: 320449



Photo 3 Stained soil PU exhaust pipe

