

## Inspection Photos

Location Name: 05-103-08524 (C & K 1-18)

Location ID: 315455

Inspection: 679701488



location



Weeds in pit and around separator