

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Oct 19, 2018 1:24:32 PM MDT
Server Receive Date:	Oct 19, 2018 1:24:59 PM MDT
Reference Number:	20181019-1889805487
Location:	557 Airpark Dr, Durango, CO 81303, USA Oct 19, 2018 1:24:26 PM MDT [View Map]

Information

Name	reclamationtablet
Date	Oct 18, 2018
Well Name	MOFFETT GAS UNIT B 1A
Location Name (Other)	Spanish Fork A4
API Number	50670671400
Location API (Other)	050670967400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Erosion Repairs Install Wattles Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Completed work description
Notes

installed erosion logs on south slopes
removed kochia debris on south slopes near
equipment