

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2018

Submitted Date:

10/19/2018

Document Number:

690900038**FIELD INSPECTION FORM**Loc ID 449274 Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Laird, Spence		sandridgeenvironmental@sandridgeenergy.com	
Church, Matt		mchurch@sandridgeenergy.com	
Waldron, Emily		emily.waldron@state.co.us	
Hewins, Grant		ghewins@sandridgeenergy.com	

**General Comment:**

On October 10, 2018, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration & Production LLC's (SandRidge) Rabbit Ears 06851 23 Location (Location ID: 449274) and API 057-06598. Weather was partially cloudy and temperatures about 29 degrees Fahrenheit with approximately 3-inches of snow on the ground

The following is a summary:

- Enclosed frac tank located adjacent to API 057-06598. Tank was placard, but not labeled.
- Load in/load out hose open ended resting on concrete barrier.
- Apparent hydrocarbon sheen noted on snow melt water in front of tank battery and load in/load out area.
- 3- 675 bbl PR water tanks.
- 5- 675 bbl Oil tanks.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	• Enclosed frac tank located adjacent to API 057-06598. Tank was placard, but not labeled.		
Corrective Action:	Comply with Rule 210.d.	Date:	11/19/2018

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: \_\_\_\_\_

Comment: Apparent hydrocarbon sheen noted on snow melt water in front of tank battery and load in/load out area.

Corrective Action: Train and educate staff and contract personnel on house keeping with zero spills, drips, beneath valves, fittings, unions, and load out area.

Date: 11/18/2018

Reportable: NO

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water:

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>On October 10, 2018, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration &amp; Production LLC's (SandRidge) Rabbit Ears 06851 23 Location (Location ID: 449274) and API 057-06598. Weather was partially cloudy and temperatures about 29 degrees Fahrenheit with approximately 3-inches of snow on the ground</p> <p>The following is a summary:</p> <ul style="list-style-type: none"> <li>• Enclosed frac tank located adjacent to API 057-06598. Tank was placard, but not labeled.</li> <li>• Load in/load out hose open ended resting on concrete barrier.</li> <li>• Apparent hydrocarbon sheen noted on snow melt water in front of tank battery and load in/load out area.</li> <li>• 3- 675 bbl PR water tanks.</li> <li>• 5- 675 bbl Oil tanks.</li> </ul> <p>Corrective Actions (CAs):</p> <ul style="list-style-type: none"> <li>• By November 19, 2018 – Signs and Markers Tanks and Containers Comply with Rule 210.d.</li> </ul> <p>Train and educate staff and contract personnel on house keeping with zero spills, drips, beneath valves, fittings, unions, and load out area.</p>	fischera	10/19/2018

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401803311	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615614">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615614</a>
690900039	20181010 SandRidge Inspection Rabbit Ears Location ID 449274	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615611">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615611</a>
690900040	INSP Photo Rabbit Ears Location 449274 20181010	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615612">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615612</a>