

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401791643

Receive Date:

10/22/2018

Report taken by:

KRIS NEIDEL

## Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

### OPERATOR INFORMATION

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC	Operator No: 10598	<b>Phone Numbers</b>
Address: 123 ROBERT S KERR AVE		Phone: (405) 4295745
City: OKLAHOMA CITY State: OK Zip: 73102		Mobile: (405) 6516853
Contact Person: Matt Church	Email: mchurch@sandridgeenergy.com	

### PROJECT, PURPOSE & SITE INFORMATION

#### PROJECT INFORMATION

Remediation Project #: 11990

Initial Form 27 Document #: 401791643

#### PURPOSE INFORMATION

- |  |  |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination                                       | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water                   |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure                             | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation                 | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project                                  |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste                      | <input type="checkbox"/> Rule 906.c.: Director request   |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____   |

#### SITE INFORMATION

N Multiple Facilities ( in accordance with Rule 909.c. )

Facility Type: SPILL OR RELEASE	Facility ID: 457247	API #: _____	County Name: JACKSON
Facility Name: SPILL/RELEASE POINT	Latitude: 40.585015	Longitude: -106.387129	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: SWSW	Sec: 9	Twp: 7N	Range: 80W Meridian: 6 Sensitive Area? Yes

#### SITE CONDITIONS

General soil type - USCS Classifications GM Most Sensitive Adjacent Land Use Grazing/Rangeland

Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? Yes

Other Potential Receptors within 1/4 mile

## SITE INVESTIGATION PLAN

### TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☒ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

### DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	Approximately 5,000 square feet	Form 19 Supplemental Investigation

### INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Initial Form 19 was submitted 9/4/2018. A Supplemental Form 19 was submitted 9/11/2018 and on 9/28/2018. The Gregory/Castle Pad is currently active and is being returned to operational. Once complete, further excavation will be initiated as requested by the Form 19 Supplemental (401782498) COA: "Further investigation around the area identified as "SDE\_GC\_SS\_39" should be completed".

### PROPOSED SAMPLING PLAN

#### Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? ( Number, type (grab/composite), analyses, and locations of samples ):

At least 3 confirmation grab samples will be collected from the excavation bottom to confirm remaining soil is below Table 910-1 acceptable concentrations. One sample will match the SDE\_GC\_SS\_39 location.

#### Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

#### Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? ( Number, analyses, and locations of samples ):

#### Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan ( summary ):

# SITE INVESTIGATION REPORT

## SAMPLE SUMMARY

### Soil

Number of soil samples collected 7

Number of soil samples exceeding 910-1 1

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 50

### NA / ND

--            Highest concentration of TPH (mg/kg) 806.1  
           39

--            Highest concentration of SAR 16

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 1

### Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet) 20'

Number of groundwater monitoring wells installed 0

Number of groundwater samples exceeding 910-1 0

NA            Highest concentration of Benzene (µg/l)           

NA            Highest concentration of Toluene (µg/l)           

NA            Highest concentration of Ethylbenzene (µg/l)           

NA            Highest concentration of Xylene (µg/l)           

NA            Highest concentration of Methane (mg/l)           

### Surface Water

0 Number of surface water samples collected

0 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

## OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)           

Volume of liquid waste (barrels)           

☐ Is further site investigation required?

# REMEDIAL ACTION PLAN

## SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

SandRidge has elected to conduct source removal of the impacted soil via dig and haul activities, scheduled to be done by November 1, 2018.

## REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

During dig and haul activities, soils from the excavation bottom will be screened for the presence of hydrocarbons with a photoionization detector (PID). Confirmation soil samples will be collected on the excavation bottom where the highest PID reading was detected (if applicable) at 15-foot intervals for BTEX, TPH-GRO, and TPH-DRO to determine that all impacted material have been properly removed. Impacted materials will be disposed of at a properly licensed disposal facility. Clean backfill material will be imported when confirmation soil samples confirm all impacted materials have been removed.

## Soil Remediation Summary

☐ In Situ

☒ Ex Situ

\_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

Yes \_\_\_\_\_ Excavate and offsite disposal

\_\_\_\_\_ Chemical oxidation

If Yes: Estimated Volume (Cubic Yards) \_\_\_\_\_ 150

\_\_\_\_\_ Air sparge / Soil vapor extraction

Name of Licensed Disposal Facility or COGCC Facility ID # \_\_\_\_\_ 211979

\_\_\_\_\_ Natural Attenuation

\_\_\_\_\_ Excavate and onsite remediation

\_\_\_\_\_ Other \_\_\_\_\_

\_\_\_\_\_ Land Treatment

\_\_\_\_\_ Bioremediation (or enhanced bioremediation)

\_\_\_\_\_ Chemical oxidation

\_\_\_\_\_ Other \_\_\_\_\_

## Groundwater Remediation Summary

☐ \_\_\_\_\_ Bioremediation ( or enhanced bioremediation )

☐ \_\_\_\_\_ Chemical oxidation

☐ \_\_\_\_\_ Air sparge / Soil vapor extraction

☐ \_\_\_\_\_ Natural Attenuation

☐ \_\_\_\_\_ Other \_\_\_\_\_

## GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

## REMEDATION PROGRESS UPDATE

### PERIODIC REPORTING

**Frequency:** ☐ Quarterly ☐ Semi-Annually ☐ Annually ☐ Other \_\_\_\_\_

**Report Type:** ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report  
☐ Other \_\_\_\_\_

### WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? \_\_\_\_\_

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards \_\_\_\_\_

E&P waste (solid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

Volume of E&P Waste (liquid) in barrels \_\_\_\_\_

E&P waste (liquid) description \_\_\_\_\_

COGCC Disposal Facility ID #, if applicable: \_\_\_\_\_

Non-COGCC Disposal Facility: \_\_\_\_\_

## RECLAMATION PLAN

### RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The facility is presently in use. Reclamation activities are not warranted at this time.

Is the described reclamation complete? \_\_\_\_\_

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? \_\_\_\_\_

If NO, does the seed mix comply with local soil conservation district recommendations? \_\_\_\_\_

## IMPLEMENTATION SCHEDULE

### PRIOR DATES

Date of Surface Owner notification/consultation, if required. 09/01/2018

Actual Spill or Release date, if known. 09/01/2018

### SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 09/04/2018

Date of commencement of Site Investigation. 09/14/2018

Date of completion of Site Investigation. 09/26/2018

### REMEDIAL ACTION DATES

Date of commencement of Remediation. 11/01/2018

Date of completion of Remediation. 11/07/2018

### SITE RECLAMATION DATES

Date of commencement of Reclamation. \_\_\_\_\_

Date of completion of Reclamation. \_\_\_\_\_

**OPERATOR COMMENT**

--

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: ` Joel Mason \_\_\_\_\_

Title: Project Manager \_\_\_\_\_

Submit Date: ` 10/22/2018 \_\_\_\_\_

Email: joel.mason@absarokasolutions.com \_\_\_\_\_

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRIS NEIDEL \_\_\_\_\_

Date: 10/26/2018 \_\_\_\_\_

Remediation Project Number: 11990 \_\_\_\_\_

**COA Type****Description**

	Location of investigation appear appropriate, however Rule 910.b(3)B should be considered when selecting specific sample location.
--	--

**Attachment Check List**

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

**Att Doc Num****Name**

401791643	FORM 27-INITIAL-SUBMITTED
401791775	SOIL SAMPLE LOCATION MAP

Total Attach: 2 Files

**General Comments****User Group****Comment****Comment Date**

Environmental	See spill number 457247 for details of soil investigation as a result of the spill that caused the contamination being remediated in this project.	10/25/2018
Environmental	Soil Sample location map states, "area requiring further reclamation" It is understood that this is the area requiring further remediation.	10/22/2018
Environmental	It is stated in the Remedial Action Plan tab, Soil Remediation Summary that 150 cubic yards of material was transported to COGCC Facility ID 211979. What is this Facility?	10/22/2018

Total: 3 comment(s)