

Inspection Photos  
Location Name: Elits-Bradley 1-14  
API: 05-107-06142



**Photo 1. Overview of location taken at entrance facing east.**



**Photo 2. No secondary containment.**



Inspection Photos  
Location Name: Elits-Bradley 1-14  
API: 05-107-06142



Photo 3. Stained soil at wellhead.



Photo 4. Stained soil in tank battery berm.



Inspection Photos  
Location Name: Elits-Bradley 1-14  
API: 05-107-06142



**Photo 5. Stained soil in tank battery berm.**



**Photo 6. Stained soil in tank battery berm.**

Inspection Photos  
Location Name: Elits-Bradley 1-14  
API: 05-107-06142



**Photo 7. Stained soil in tank battery berm.**



**Photo 8. Stained soil in tank battery berm.**