

N
5JK

LEASE INSPECTION FORM

Operator WINSLOW RKS Date 10/28/86
Lease Name & No. TIME # 1 Field TIME
Tank Battery No. INCORRECT County MORGAN
Location SW NE 6-1N-56W
Legal Description
Type of Inspection PIT
Water Inflow 1 FINGER = 100 BBL/DAY (Bbls. Per Day)

RESULTS OF INSPECTION

(Est. Pit Dimensions, CVD, Lined, Oil on Surface, etc.)
Type of Tank

SKIM TANK 2-300 BBL STEEL

Pit No. 1 H-T

Pit No. 2 1000 gal CMT

Pit No. 3 50 X 50, OPER, BLK PVC BURIED UNDER DIRT, C/W #20

ADDITIONAL PITS _____

CONDITION OF LEASE (Describe - Oil CVD. or Sat. Gr., Any Leaking, Safety Conditions, Etc.)

PUMPSACK OPERATIONAL

RECOMMENDED ACTION (If Required) TANK ID, LEASE SIGN

INSPECTOR 5JK