

Inspection Photos

Location Name: 05-103-110XX (BOIES A-29D-XXXX)

Location ID: 335629

Inspection: 679701532



Location wells




Location separators

Inspection Photos

Location Name: 05-103-110XX (BOIES A-29D-XXXX)

Location ID: 335629

Inspection: 679701532



Location tanks



Labels on container next to separators are too faded to read

Inspection Photos

Location Name: 05-103-110XX (BOIES A-29D-XXXX)

Location ID: 335629

Inspection: 679701532



Deadman without marker



No signs on location have "Public access road CR 29"

